
View Message







Motorcycle National Field Service

July 14, 2015

SERVICE BULLETIN: Multiple Models - Starter Relay Switch Inspection/Replacement

Dear Honda Powersports Dealer:

The Service Bulletin in support of the SAFETY RECALL of **Multiple Models** for a potentially defective **Starter Relay Switch** is posted on **iN**.

To search for applicable recalls on a specific unit, use *Unit Information* on *iN*. To manage your affected inventory, use *eResponsibility Report*.

Reminder: Affected units that pass the inspection procedure outlined in the Service Bulletin can be sold. Be sure to file a warranty claim using the correct Claim Template as outlined in the bulletin.

SERVICE BULLETIN

<u>SAFETY RECALL: Multiple Models - Starter Relay Switch Inspection/Replacement</u> includes the affected models and VIN ranges, inspection procedure, repair procedure, parts information, as well as warranty claim information.

CUSTOMER NOTIFICATION

AHM intends to mail customer letters around August 14, 2015 based on vehicle registration information.

PARTS INFORMATION

- Through mid-August, the repair parts supply will be extremely limited.
- An initial limited allocation of repair parts, based upon your dealership's affected inventory and sold units, will begin shipping in early August.
- When repair parts supplies are sufficient to repair all dealer and customer units, parts will be available on open order.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact Motorcycle TechLine at 1 (800) 421-1900, Option 9; through TechLine Connect on *iN*; or contact your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.

Bradley Little

Manager, National Field Service

Motorcycle Division

Bulletin Number: 15-0198

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.